



ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ, ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2

ਲੋਕ ਨਿਰਮਾਣ ਵਿਭਾਗ (ਭ ਤੇ ਮ) ਸ਼ਾਖਾ, ਬਠਿੰਡਾ।

ਫੋਨ ਅਤੇ ਫੈਕਸ: 0164-2212428

email: - xenc2bti@gmail.com

ਮੀਮੋ ਨੰ: 359

ਮਿਤੀ: 22/04/2024

ਵੱਲ

Principal
Bhai Daan Singh Academy,
Daan Singh Wala, Distt. Bathinda

ਵਿਸ਼ਾ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕਰਨ ਸਬੰਧੀ।

ਉਪਰੋਕਤ ਵਿਸ਼ੇ ਦੇ ਸਬੰਧ ਵਿੱਚ ਆਪ ਨੂੰ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੇ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਦਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਨਿਰੀਖਣ ਕੀਤਾ ਗਿਆ, ਨਿਰੀਖਣ ਦੌਰਾਨ ਪਾਇਆ ਗਿਆ ਹੈ ਕਿ ਸਕੂਲ ਦੀ ਬਿਲਡਿੰਗ ਸੇਫ ਹੈ। ਇਸ ਲਈ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਵੱਲੋਂ ਕੀਤੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਹੇਠ ਲਿਖੀਆਂ ਸ਼ਰਤਾਂ ਅਧੀਨ 31.03.2025 ਤੱਕ ਸਕੂਲ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ:-

- The Structure safety Certificate dated 06.04.2024 is provided by Er. Rubal Singla, M.tech (Civil) Bathinda and as per his certificate the school is safe to be occupied for session 2024-25 and is fit for normal use only, however no structure drawing approved as per earthquake resistant norms has been provided by the school authority hence the structural safety of the building can not be ensured specially from earthquake point of view by this department.
- In case any addition, alteration, expansion and modification to this building are required / to be done, regarding this, inspection of undersigned must be arranged and fresh a certification after the completion from the undersigned.
- In the case of building is affected by flood or if there is any settlement of wall foundation etc. Immediately inspection of the undersigned must be arranged to check the stability and safety of the building.
- A separate certificate regarding Electrical works should be obtained from the competent authority.
- 4A. Fire Fighting Certificate should be obtained from competent authority and it should be renew time to time. If the certificate will not be renewed then this office building safety certificate becomes invalid from the very date. In this case Fire Safety Certificate renewal date is 20.06.2024**
- The owner of the building/Management should be responsible to address any repair issues that could compromise the safety of the building, in spite of this report the school management is fully responsible regarding safety of the building from all angles.
- The school should have a comprehensive emergency response plan in place, including procedures for evacuation, lockdowns, and communication during emergencies. The school must regularly review and update this plan to ensure its effectiveness.
- The school should provide appropriate safety training to staff members, including procedures for handling emergencies, first aid, and evacuation protocols.
- The fee has been charged for the area as mentioned in the drawing by the school authority. The corresponding fee charges for the year 2024-25 Rs. 10,000/-Only (in words Ten Thousand only) vide GR No. 1744723
- This report is not valid for legal purpose.

ਨੱਥੀ/ਸਰਟੀਫਿਕੇਟ ਅਤੇ ਨਕਸ਼ਾ

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ
ਉਸਾਰੀ ਮੰਡਲ ਨੰ:2 ਭ ਤੇ ਮ ਸ਼ਾਖਾ
ਬਠਿੰਡਾ

ਪਿੱਠ ਅੰਕਣ:-

ਮਿਤੀ:-

ਉਪਰੋਕਤ ਦਾ ਉਤਾਰਾ ਉਪ ਮੰਡਲ ਇੰਜੀਨੀਅਰ ਉਸਾਰੀ ਉਪ ਮੰਡਲ ਭ ਤੇ ਮ ਸ਼ਾਖਾ ਗੋਨਿਆਣਾ ਐਟ ਬਠਿੰਡਾ ਨੂੰ ਉਹਨਾਂ ਦੇ ਦਫਤਰ ਦੇ ਪੱਤਰ ਨੰ. 19 ਮਿਤੀ 19.04.2024 ਦੇ ਸਬੰਧ ਵਿੱਚ ਭੇਜ ਕੇ ਲਿਖਿਆ ਜਾਂਦਾ ਹੈ ਕਿ ਆਪ ਦੀ ਸਿਫਾਰਸ਼ ਨੂੰ ਮੁੱਖ ਰੱਖਦੇ ਹੋਏ ਉਕਤ ਸਕੂਲ ਨੂੰ ਬਿਲਡਿੰਗ ਸੇਫਟੀ ਸਰਟੀਫਿਕੇਟ ਜਾਰੀ ਕੀਤਾ ਜਾਂਦਾ ਹੈ।

ਕਾਰਜਕਾਰੀ ਇੰਜੀਨੀਅਰ